


# Safety Share – Fire Extinguisher Explosion



# Safety Share

Arrows point to bolt location



# Safety Share

---



Fatigue cracking

Third extinguisher showing wear from bracket strap rubbing

# Safety Share

---

Burton – Checks found this FE with a corroded base – another potential bomb!

